

The selected address: 3569 DEKALB AVENUE, Bronx 10467

This building has filed records with the [New York State Division of Housing and Community Renewal](#) at least one time from 1993 to the present year and may contain one or more regulated apartments.

HPD#	Range	Block	Lot	CD	CensusTract	Stories	A Units	B Units	Ownership	Registration#	Class	
61064	Active	3569-3569	03329	0040	7	43100	6	54	0	PVT	200894	B

- Other Units
- Property Owner Registration Information
- Charges
- Completed Status
- Complaint History
- Litigation/Case Status
- Tenant Harassment Report
- All Open Violations
- prior year Open Viol's
- Escrow/Lease
- Overdue Lead Paint Viol Correction
- Vacate Orders
- L-Card Issues
- PROS Orders
- Bed Bugs
- Map

### Building Registration Summary Report

Find Apartment#

Owner	Last Reg Dt	Reg Expir Dt	Organization	Last Nm	First Nm	House No	Street Nm	Apt	City	State	Zip
Head Officer	08/20/2019	09/01/2020		RAPHAEL	ROBERT	55	WATERMILL LANE	100	Great Neck	NY	11021
Corporation	08/20/2019	09/01/2020	NY AFFORDABLE HOUSING DEKALB ASSOCIATES LLC			55	WATERMILL LANE	100	Great Neck	NY	11021
Managing Agent	08/20/2019	09/01/2020	GILMAN MANAGEMENT CORP.	COLON	NELSON	265	LAFAYETTE STREET	4G	New York	NY	10012
Partner/Member	08/20/2019	09/01/2020		SCHWARTZ	MARK	55	WATERMILL LANE	100	Great Neck	NY	11021
Partner/Member	08/20/2019	09/01/2020		BLUMENFRUCHT	MARC	459	COLUMBUS AVE	700	NEW YORK	NY	10024

#### Open Violations - ALL DATES

There are 245 Violations. Arranged by category: A class: 39 B class: 156 C class: 49 I class: 1

For Definitions of the columns indicated below, select glossary under the Services option (located at the upper right).

To sort the columns, click on their underlined headers below in the blue area.

Apt Story	<u>Reported Date</u> nov ISSUED Date	<u>Hzrd Class</u>	<u>Order no</u>	<u>Violation ID</u> NOV ID NOV Type	Violation Description	<u>Status</u> Status Date	Certify By Date Actual Cert. Date
3J 4	2019/11/07 2019/11/12	A	556	13447750 6727008 Original	§ 27-2013 adm code paint with light colored paint to the satisfaction of this department all peeling paint surfaces in the 2nd room from north, the bathroom , the private hallway , the foyer , the kitchenette located at apt 3j, 4th story, 1st apartment from west at north	NOV SENT 2019/11/12	2020/02/29
3J 4	2019/11/07 2019/11/12	B	501	13431871 6727009 Original	§ 27-2005 adm code properly repair the broken or defective ceiling light fixture in the bathroom located at apt 3j, 4th story, 1st apartment from west at north	NOV SENT 2019/11/12	2019/12/31
3J 4	2019/11/07 2019/11/12	C	569	13431872 6727011 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of mice in the entire apartment located at apt 3j, 4th story, 1st apartment from west at north	NOI SENT 2019/11/12	2019/12/08
3J 4	2019/11/07 2019/11/12	B	508	13431873 6727009 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color the ceiling, north wall, east wall, south wall, west wall in the 1st room from north at west located at apt 3j, 4th story, 1st apartment from west at north	NOV SENT 2019/11/12	2019/12/31
3J 4	2019/11/07 2019/11/12	C	617	13447749 6727010 Original	§ 27-2056.6 adm code - correct the lead-based paint hazard - paint that tested positive for lead content and that is peeling or on a deteriorated subsurface - using work practices set forth in 28 rcny §11-06(b)(2) 1st window frame from south at west wall in the 1st room from north at west located at apt 3j, 4th story, 1st apartment from west at north	NOV SENT 2019/11/12	2019/12/15
M 1	2019/10/24 2019/10/28	A	508	13363644 6655124 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color all walls and ceiling in the foyer located at apt m, 1st story, 1st apartment from north at east , section "n+m"	NOV SENT 2019/10/28	2020/02/14
M 1	2019/10/24 2019/10/28	B	508	13363645 6655125 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color the ceiling in the kitchen located at apt m, 1st story, 1st apartment from north at east , section "n+m"	NOV SENT 2019/10/28	2019/12/16

M 1	2019/10/24 2019/10/28	B	502	13363646 6655125 Original	§ 27-2005 adm code properly repair with similar material the broken or defective plywood floor in the 1st room from north located at apt m, 1st story, 1st apartment from north at east , section "n+m"	NOV SENT 2019/10/28	2019/12/16
M 1	2019/10/24 2019/10/28	A	502	13363648 6655124 Original	§ 27-2005 adm code properly repair with similar material the broken or defective vinyl floor tiles in the 1st room from north located at apt m, 1st story, 1st apartment from north at east , section "n+m"	NOV SENT 2019/10/28	2020/02/14
M 1	2019/10/24 2019/10/28	B	502	13363652 6655125 Original	§ 27-2005 adm code properly repair with similar material the broken or defective plywood floor in the 2nd room from north located at apt m, 1st story, 1st apartment from north at east , section "n+m"	NOV SENT 2019/10/28	2019/12/16
M 1	2019/10/24 2019/10/28	A	502	13363653 6655124 Original	§ 27-2005 adm code properly repair with similar material the broken or defective vinyl floor tiles in the 2nd room from north located at apt m, 1st story, 1st apartment from north at east , section "n+m"	NOV SENT 2019/10/28	2020/02/14
M 1	2019/10/24 2019/10/28	C	569	13363655 6655127 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of mice in the entire apartment located at apt m, 1st story, 1st apartment from north at east , section "n+m"	NOI SENT 2019/10/28	2019/11/23
M 1	2019/10/24 2019/10/28	B	583	13363656 6655125 Original	§ 27-2026, 2027 hmc: properly repair the source and abate the evidence of a water leak at ceiling in the bathroom located at apt m, 1st story, 1st apartment from north at east , section "n+m"	NOV SENT 2019/10/28	2019/12/16
M 1	2019/10/24 2019/10/28	A	550	13363658 6655126 Original	§ 27-2017.3 hmc: trace and repair the source and abate the visible mold condition... approx 1 square foot at ceiling in the bathroom located at apt m, 1st story, 1st apartment from north at east , section "n+m"	NOI SENT 2019/10/28	2020/02/14
M 1	2019/10/24 2019/10/28	A	508	13363659 6655124 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color the ceiling and east wall in the bathroom located at apt m, 1st story, 1st apartment from north at east , section "n+m"	NOV SENT 2019/10/28	2020/02/14
M 1	2019/10/24 2019/10/28	B	1503	13363662 6655125 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s). defective located at apt m, 1st story, 1st apartment from north at east , section "n+m"	NOV SENT 2019/10/28	2019/12/16
M 1	2019/10/24 2019/10/28	B	702	13363665 6655125 Original	§ 27-2045 adm code repair or replace the smoke detector defective located at apt m, 1st story, 1st apartment from north at east , section "n+m"	NOV SENT 2019/10/28	2019/12/16
2D 2	2019/10/17 2019/10/21	B	508	13343665 6639605 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color at west wall in the bathroom located at apt 2d, 2nd story, 1st apartment from south at west	NOV SENT 2019/10/21	2019/12/09
2D 4	2019/10/02 2019/10/03	C	568	13313577 6623685 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of roaches in the entire apartment located at apt 2d, 4th story, 1st apartment from south at west	NOI SENT 2019/10/03	2019/10/29
2D 4	2019/10/02 2019/10/03	C	569	13313578 6623685 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of mice in the entire apartment located at apt 2d, 4th story, 1st apartment from south at west	NOI SENT 2019/10/03	2019/10/29
2D 4	2019/10/02 2019/10/03	B	1503	13313586 6623684 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s). defective located at apt 2d, 4th story, 1st apartment from south at west	NOV SENT 2019/10/03	2019/11/21
2D 4	2019/10/02 2019/10/03	B	702	13313593 6623684 Original	§ 27-2045 adm code repair or replace the smoke detector defective located at apt 2d, 4th story, 1st apartment from south at west	NOV SENT 2019/10/03	2019/11/21
2D 4	2019/10/02 2019/10/03	C	530	13313614 6623686 Original	§ 27-2005, 2007 adm code arrange and make self-closing the doors door not self closing in the entrance located at apt 2d, 4th story, 1st apartment from south at west	NOV SENT 2019/10/03	2019/10/29
3A 5	2019/09/25 2019/09/27	B	702	13300108 6617567 Original	§ 27-2045 adm code repair or replace the smoke detector defective in the entire apartment located at apt 3a, 5th story, 2nd apartment from north at east	NOV SENT 2019/09/27	2019/11/15
3A 5	2019/09/25 2019/09/27	B	1503	13300113 6617567 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s). defective in the entire apartment located at apt 3a, 5th story, 2nd apartment from north at east	NOV SENT 2019/09/27	2019/11/15
3A 5	2019/09/25 2019/09/27	C	790	13300117 6617568 Original	§ 27-2043.1 hmc install the missing or repair/replace the defective window guard(s) in accordance with the specifications of the new york city health code section 24 rcny chapter 12. wg to install = 1; wg to replace = 0; wg to repair = 0; in the entire apartment located at apt 3a, 5th story, 2nd apartment from north at east	NOV SENT 2019/09/27	2019/10/30
E 2	2019/09/25 2019/09/27	B	702	13300159 6617569 Original	§ 27-2045 adm code repair or replace the smoke detector missing in the entire apartment located at apt e, 2nd story, 2nd apartment from south at west	NOV SENT 2019/09/27	2019/11/15

E 2	2019/09/25 2019/09/27	B	1503	13300167 6617569 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s). missing in the entire apartment located at apt e, 2nd story, 2nd apartment from south at west	NOV SENT 2019/09/27	2019/11/15
E 2	2019/09/25 2019/09/27	B	550	13300183 6617570 Original	§ 27-2017.3 hmc: trace and repair the source and abate the visible mold condition... at ceiling approx. 15 sq.ft in the 2nd room from north located at apt e, 2nd story, 2nd apartment from south at west	NOI SENT 2019/09/27	2019/11/15
E 2	2019/09/25 2019/09/27	B	583	13300185 6617569 Original	§ 27-2026, 2027 hmc: properly repair the source and abate the evidence of a water leak at ceiling in the 2nd room from north located at apt e, 2nd story, 2nd apartment from south at west	NOV SENT 2019/09/27	2019/11/15
4J 6	2019/09/25 2019/09/27	C	530	13300280 6617571 Original	§ 27-2005, 2007 adm code arrange and make self-closing the doors at entrance in the entrance located at apt 4j, 6th story, 1st apartment from north at east	NOV SENT 2019/09/27	2019/10/23
2J 4	2019/09/25 2019/09/27	B	702	13300310 6617572 Original	§ 27-2045 adm code repair or replace the smoke detector defective in the entire apartment located at apt 2j, 4th story, 1st apartment from west at north	NOV SENT 2019/09/27	2019/11/15
2J 4	2019/09/25 2019/09/27	B	1503	13300319 6617572 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s). defective in the entire apartment located at apt 2j, 4th story, 1st apartment from west at north	NOV SENT 2019/09/27	2019/11/15
2J 4	2019/09/25 2019/09/27	C	546	13300348 6617573 Original	§ 27-2005, 2007 hmc: remove the illegal double cylinder key operated locking device at door lock installed at door leading to fire escape exit in the 1st room from north located at apt 2j, 4th story, 1st apartment from west at north	NOV SENT 2019/09/27	2019/10/10
1J 3	2019/09/23 2019/09/26	C	568	13299155 6615843 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of roaches in the entire apartment located at apt 1j, 3rd story, 1st apartment from west at north	NOI SENT 2019/09/26	2019/10/22
A 1	2019/09/23 2019/09/25	C	530	13295822 6614706 Original	§ 27-2005, 2007 adm code arrange and make self-closing the doors .. in the entrance located at apt a, 1st story, 2nd apartment from north at east	NOV SENT 2019/09/25	2019/10/21
A 1	2019/09/23 2019/09/25	B	502	13295823 6614705 Original	§ 27-2005 adm code properly repair with similar material the broken or defective rotted woor floor and vinyl tiles in the 2nd room from east located at apt a, 1st story, 2nd apartment from north at east	NOV SENT 2019/09/25	2019/11/13
A 1	2019/09/23 2019/09/25	A	556	13295824 6614704 Original	§ 27-2013 adm code paint with light colored paint to the satisfaction of this department at ceiling and walls in the bathroom located at apt a, 1st story, 2nd apartment from north at east	NOV SENT 2019/09/25	2020/01/12
A 2	2019/09/19 2019/09/23	B	583	13290685 6611174 Original	§ 27-2026, 2027 hmc: properly repair the source and abate the evidence of a water leak at south wall in the 1st room from east located at apt a, 2nd story, 2nd apartment from north at east	NOV SENT 2019/09/23	2019/11/11
1A 3	2019/09/19 2019/09/23	B	583	13290696 6611175 Original	§ 27-2026, 2027 hmc: properly repair the source and abate the evidence of a water leak at ceiling in the bathroom located at apt 1a, 3rd story, 1st apartment from north at east	NOV SENT 2019/09/23	2019/11/11
4I 6	2019/09/19 2019/09/23	B	583	13290707 6611176 Original	§ 27-2026, 2027 hmc: properly repair the source and abate the evidence of a water leak at ceiling in the bathroom located at apt 4i, 6th story, 1st apartment from south at west	NOV SENT 2019/09/23	2019/11/11
1G 3	2019/09/20 2019/09/23	B	583	13292759 6612108 Original	§ 27-2026, 2027 hmc: properly repair the source and abate the evidence of a water leak at ceiling and south wall in the bathroom located at apt 1g, 3rd story, 2nd apartment from north at east	NOV SENT 2019/09/23	2019/11/11
1F 3	2019/09/17 2019/09/19	C	790	13284871 6608372 Original	§ 27-2043.1 hmc install the missing or repair/replace the defective window guard(s) in accordance with the specifications of the new york city health code section 24 rcny chapter 12. wg to install = 1; wg to replace = 0; wg to repair = 0; in the entire apartment located at apt 1f, 3rd story, 1st apartment from north at east , 1st section from east at south	NOV SENT 2019/09/19	2019/10/22
	2019/09/17 2019/09/19	C	510	13284878 6608371 Original	§ 27-2005 adm code & 309 m/d law abate the nuisance consisting of an air conditioner at the fire escape window, 1st stack from west at south, 2nd story.	NOV SENT 2019/09/19	2019/10/02
	2019/09/17 2019/09/19	C	510	13284911 6608371 Original	§ 27-2005 adm code & 309 m/d law abate the nuisance consisting of an air conditioner in the window, 1st stack from west at south, 5th story.	NOV SENT 2019/09/19	2019/10/02
Fire Escape	2019/09/12 2019/09/16	B	539	13277728 6604036 Original	§ 27-2005, 2007 adm code and dept. rules and regulations. remove the encumbrance obstructing egress from fire escapes consists of flower pot at 3rd story balcony at north stack building front	NOV SENT 2019/09/16	2019/11/04
Fire Escape	2019/09/12 2019/09/16	C	510	13277760 6604037 Original	§ 27-2005 adm code & 309 m/d law abate the nuisance consisting of air conditioner at window leading to the fire escape exit at 4th story north stack building front	NOT COMPLIED 2019/09/20	2019/09/29

Roof	2019/09/10 2019/09/12	B	506	13274949 6601398 Original	§ 27-2005 adm code replace with new the missing terra cota copping at west parapet wall center roof	NOV SENT 2019/09/12	2019/10/31
Yards / Courts	2019/09/10 2019/09/12	B	658	13274953 6601398 Original	§ 27-2005 adm code properly repair the broken or defective paving at rear west outter court yard	NOV SENT 2019/09/12	2019/10/31
All Stories	2019/09/10 2019/09/12	B	502	13274956 6601398 Original	§ 27-2005 adm code properly repair with similar material the broken or defective 2nd concrete tread up from side walk bldg front entrance outter court	NOV SENT 2019/09/12	2019/10/31
3	2019/09/04 2019/09/09	B	539	13263370 6597501 Original	§ 27-2005, 2007 adm code and dept. rules and regulations. remove the encumbrance obstructing egress from fire escapes flowers pots, at front at 1st fire escape from north, 3rd story	NOV SENT 2019/09/09	2019/10/28
Fire Escape	2019/09/03 2019/09/05	B	539	13260861 6594279 Original	§ 27-2005, 2007 adm code and dept. rules and regulations. remove the encumbrance obstructing egress from fire escapes consists of flower pots at 3rd story bakony at north stack building front	NOV SENT 2019/09/05	2019/10/24
A 2	2019/09/03 2019/09/05	A	550	13261926 6594281 Original	§ 27-2017.3 hmc: trace and repair the source and abate the visible mold condition... south wall, west wall and ceiling in the bathroom located at apt a, 2nd story, 2nd apartment from north at east	NOI SENT 2019/09/05	2019/12/23
2J 4	2019/09/03 2019/09/05	B	1503	13261981 6594283 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s). defective in the entire apartment located at apt 2j, 4th story, 1st apartment from west at north	NOV SENT 2019/09/05	2019/10/24
2J 4	2019/09/03 2019/09/05	B	702	13261983 6594283 Original	§ 27-2045 adm code repair or replace the smoke detector defective in the entire apartment located at apt 2j, 4th story, 1st apartment from west at north	NOV SENT 2019/09/05	2019/10/24
2J 4	2019/09/03 2019/09/05	C	568	13261985 6594284 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of roaches in the entire apartment located at apt 2j, 4th story, 1st apartment from west at north	NOT COMPLIED 2019/09/26	2019/10/01
2J 4	2019/09/03 2019/09/05	C	569	13261986 6594284 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of mice in the entire apartment located at apt 2j, 4th story, 1st apartment from west at north	NOT COMPLIED 2019/09/26	2019/10/01
3A 4	2019/09/03 2019/09/05	C	568	13262004 6594286 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of roaches in the entire apartment located at apt 3a, 4th story, 1st apartment from west at north	NOT COMPLIED 2019/09/26	2019/10/01
3A 4	2019/09/03 2019/09/05	C	569	13262005 6594286 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of mice in the entire apartment located at apt 3a, 4th story, 1st apartment from west at north	NOT COMPLIED 2019/09/26	2019/10/01
3A 4	2019/09/03 2019/09/05	C	790	13262008 6594285 Original	§ 27-2043.1 hmc install the missing or repair/replace the defective window guard(s) in accordance with the specifications of the new york city health code section 24 rcny chapter 12. wg to install = 1; wg to replace = 0; wg to repair = 0; in the entire apartment located at apt 3a, 4th story, 1st apartment from west at north	NOT COMPLIED 2019/09/26	2019/10/08
4C 4	2019/09/03 2019/09/05	C	568	13262210 6594287 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of roaches in the entire apartment located at apt 4c, 4th story, 1st apartment from west at north	NOT COMPLIED 2019/09/20	2019/10/01
4C 4	2019/09/03 2019/09/05	C	569	13262211 6594287 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of mice in the entire apartment located at apt 4c, 4th story, 1st apartment from west at north	NOT COMPLIED 2019/09/20	2019/10/01
3H 5	2019/09/03 2019/09/05	C	790	13262255 6594289 Original	§ 27-2043.1 hmc install the missing or repair/replace the defective window guard(s) in accordance with the specifications of the new york city health code section 24 rcny chapter 12. wg to install = 1; wg to replace = 0; wg to repair = 0; in the entire apartment located at apt 3h, 5th story, 1st apartment from east at south	NOT COMPLIED 2019/09/21	2019/10/08
3H 5	2019/09/03 2019/09/05	C	568	13262262 6594290 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of roaches in the entire apartment located at apt 3h, 5th story, 1st apartment from east at south	NOT COMPLIED 2019/09/21	2019/10/01
3H 5	2019/09/03 2019/09/05	C	569	13262264 6594290 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of mice in the entire apartment located at apt 3h, 5th story, 1st apartment from east at south	NOT COMPLIED 2019/09/21	2019/10/01
3I 4	2019/08/20 2019/08/26	A	508	13236938 6582773 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color at ceiling in the bathroom located at apt 3i, 4th story, 1st apartment from south at west	NOV SENT 2019/08/26	2019/12/13
3I 4	2019/08/20 2019/08/26	A	502	13236985 6582773 Original	§ 27-2005 adm code properly repair with similar material the broken or defective ceramic floor tiles in the bathroom located at apt 3i, 4th story, 1st apartment from south at west	NOV SENT 2019/08/26	2019/12/13
3I 4	2019/08/20 2019/08/26	A	501	13236987 6582773 Original	§ 27-2005 adm code properly repair the broken or defective intercom in the foyer located at apt 3i, 4th story, 1st apartment from south at west	NOV SENT 2019/08/26	2019/12/13

3I 4	2019/08/20 2019/08/26	B	510	13236996 6582774 Original	§ 27-2005 adm code & 309 m/d law abate the nuisance consisting of free standing disconnected radiator heater in the 1st room from east located at apt 3i, 4th story, 1st apartment from south at west	NOV SENT 2019/08/26	2019/10/14
3I 4	2019/08/20 2019/08/26	A	556	13237001 6582773 Original	§ 27-2013 adm code paint with light colored paint to the satisfaction of this department walls and ceiling through-out in the entire apartment located at apt 3i, 4th story, 1st apartment from south at west	NOV SENT 2019/08/26	2019/12/13
3I 4	2019/08/20 2019/08/26	C	568	13237026 6582775 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of roaches in the entire apartment located at apt 3i, 4th story, 1st apartment from south at west	NOT COMPLIED 2019/09/20	2019/09/21
2	2019/08/20 2019/08/26	A	552	13237139 6582770 Original	§ 27-2010, 2011, 2012 adm code remove the accumulation of refuse and/or rubbish and maintain in a clean condition the hallway (discarded furniture and bags of trash) at public hall, 2nd story	NOV SENT 2019/08/26	2019/12/13
All Stories	2019/08/20 2019/08/26	A	553	13237153 6582770 Original	§ 27-2011 adm code cleanse to the satisfaction of this department the floors at all stories at public hall stairs	NOV SENT 2019/08/26	2019/12/13
All Stories	2019/08/20 2019/08/26	A	556	13237219 6582770 Original	§ 27-2013 adm code paint with light colored paint to the satisfaction of this department walls and ceilings at public hall stairs	NOV SENT 2019/08/26	2019/12/13
1	2019/08/20 2019/08/26	A	722	13237229 6582770 Original	§ 27-2053 adm code post sign on wall of entrance story bearing name, address including apartment number if any, and telephone number of superintendent, janitor or housekeeper. at public hall, 1st story	NOV SENT 2019/08/26	2019/12/13
2C 3	2019/08/20 2019/08/26	A	502	13237290 6582770 Original	§ 27-2005 adm code properly repair with similar material the broken or defective wood floor in the 1st room from north located at apt 2c, 3rd story, section at north	NOV SENT 2019/08/26	2019/12/13
2C 3	2019/08/20 2019/08/26	B	583	13237298 6582771 Original	§ 27-2026, 2027 hmc: properly repair the source and abate the evidence of a water leak at ceiling in the bathroom located at apt 2c, 3rd story, section at north	1 NO ACCESS 2019/09/29	2019/10/14
2C 3	2019/08/20 2019/08/26	A	508	13237302 6582770 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color at ceiling in the bathroom located at apt 2c, 3rd story, section at north	NOV SENT 2019/08/26	2019/12/13
I 1	2019/08/16 2019/08/21	B	502	13232102 6579040 Original	§ 27-2005 adm code properly repair with similar material the broken or defective rotted wood floor and vinyl floor tiles in the 2nd room from east located at apt i, 1st story, 1st apartment from south at west	NOV SENT 2019/08/21	2019/10/09
I 1	2019/08/16 2019/08/21	B	579	13232103 6579040 Original	§ 27-2026 adm code repair the leaky and/or defective faucets at sink in the kitchen located at apt i, 1st story, 1st apartment from south at west	NOV SENT 2019/08/21	2019/10/09
I 1	2019/08/16 2019/08/21	B	505	13232104 6579040 Original	§ 27-2005 adm code replace with new the broken or defective counter balances at lower window sash in the bathroom located at apt i, 1st story, 1st apartment from south at west	NOV SENT 2019/08/21	2019/10/09
I 1	2019/08/16 2019/08/21	B	502	13232106 6579040 Original	§ 27-2005 adm code properly repair with similar material the broken or defective ceramic wall tiles in the bathroom located at apt i, 1st story, 1st apartment from south at west	NOV SENT 2019/08/21	2019/10/09
I 1	2019/08/16 2019/08/21	B	502	13232326 6579040 Original	§ 27-2005 adm code properly repair with similar material the broken or defective porcelain surface at bathtub in the bathroom located at apt i, 1st story	NOV SENT 2019/08/21	2019/10/09
I 1	2019/08/16 2019/08/21	C	526 *	13232365 6579041 Original	§ 27-2005, 2007 adm code remove the illegal fastening lockable slide bolt on door at in the entrance located at apt i, 1st story, 1st apartment from south at west	1 NO ACCESS 2019/09/29	2019/09/03
I 1	2019/08/16 2019/08/21	B	702	13232376 6579040 Original	§ 27-2045 adm code repair or replace the smoke detector missing located at apt i, 1st story, 1st apartment from south at west	NOV SENT 2019/08/21	2019/10/09
I 1	2019/08/16 2019/08/21	B	1503	13232377 6579040 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s). missing located at apt i, 1st story, 1st apartment from south at west	NOV SENT 2019/08/21	2019/10/09
1	2019/08/16 2019/08/20	C	530	13232094 6578455 Original	§ 27-2005, 2007 adm code arrange and make self-closing the doors at building entrance, 1st story	OPEN 2019/09/19	2019/09/15
I 1	2019/08/16 2019/08/20	B	502	13232117 6578454 Original	§ 27-2005 adm code properly repair with similar material the broken or defective rotted wood floor and vinyl tiles in the 2nd room from east located at apt i, 1st story, 1st apartment from south at west	NOV SENT 2019/08/20	2019/10/08
3I 4	2019/08/12 2019/08/16	A	501	13228994 6574393 Original	§ 27-2005 adm code properly repair the broken or defective intercom system in the private hallway located at apt 3i, 4th story, 1st apartment from south at west, section at south	NOV SENT 2019/08/16	2019/12/03
3I 4	2019/08/12 2019/08/16	A	502	13229024 6574393 Original	§ 27-2005 adm code properly repair with similar material the broken or defective ceramic tile grout at floor in the bathroom located at apt 3i, 4th story, 1st apartment from south at west, section at south	NOV SENT 2019/08/16	2019/12/03

3I 4	2019/08/12 2019/08/16	A	556	13229025 6574393 Original	§ 27-2013 adm code paint with light colored paint to the satisfaction of this department the ceiling in the bathroom located at apt 3i, 4th story, 1st apartment from south at west , section at south	NOV SENT 2019/08/16	2019/12/03
3I 4	2019/08/12 2019/08/16	B	583	13229087 6574394 Original	§ 27-2026, 2027 hmc: properly repair the source and abate the evidence of a water leak above the ceiling in the kitchen located at apt 3i, 4th story, 1st apartment from south at west , section at south	NOT COMPLIED 2019/09/20	2019/10/04
3I 4	2019/08/12 2019/08/16	B	508	13229089 6574394 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color the ceiling and west wall in the kitchen located at apt 3i, 4th story, 1st apartment from south at west , section at south	NOV SENT 2019/08/16	2019/10/04
3I 4	2019/08/12 2019/08/16	B	505	13229094 6574394 Original	§ 27-2005 adm code replace with new the broken or defective marble saddle at entrance door to apt located at apt 3i, 4th story, 1st apartment from south at west , section at south	NOV SENT 2019/08/16	2019/10/04
All Stories	2019/08/12 2019/08/16	B	502	13229100 6574394 Original	§ 27-2005 adm code properly repair with similar material the broken or defective 4th masonry tread up from bottom at entrance outer court	NOV SENT 2019/08/16	2019/10/04
1F 3	2019/08/06 2019/08/08	C	530	13212420 6565487 Original	§ 27-2005, 2007 adm code arrange and make self-closing the doors ... in the entrance located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	OPEN 2019/09/19	2019/09/03
1F 3	2019/08/06 2019/08/08	B	1503	13212421 6565482 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s), missing in the entire apartment located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	702	13212422 6565482 Original	§ 27-2045 adm code repair or replace the smoke detector missing in the entire apartment located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	C	569	13212424 6565486 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of mice in the entire apartment located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	DEFECT LETTER 2019/09/29	2019/09/03
1F 3	2019/08/06 2019/08/08	C	568	13212425 6565486 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of roaches in the entire apartment located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	DEFECT LETTER 2019/09/29	2019/09/03
1F 3	2019/08/06 2019/08/08	B	593 *	13212427 6565482 Original	§ 27-2026 adm code repair the flushing apparatus and maintain same so as to flush effectively the water closet ... in the bathroom located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	502	13212428 6565482 Original	§ 27-2005 adm code properly repair with similar material the broken or defective reglazed porcelain bathtub in the bathroom located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	A	506	13212429 6565481 Original	§ 27-2005 adm code replace with new the missing vinyl floor tile in the 1st room from east located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/11/25
1F 3	2019/08/06 2019/08/08	B	506	13212430 6565482 Original	§ 27-2005 adm code replace with new the missing electrical outlet cover at south and north wall in the 1st room from east located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	A	506	13212431 6565481 Original	§ 27-2005 adm code replace with new the missing vinyl floor tile in the 3rd room from east located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/11/25
1F 3	2019/08/06 2019/08/08	B	506	13212432 6565482 Original	§ 27-2005 adm code replace with new the missing electrical outlet cover at west wall in the 3rd room from east located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	689	13212433 6565482 Original	§ 27-2005, 2006, 2037 hmc: properly repair and abate unsafe electric wiring condition consisting of exposed electrical wire at west wall in the 3rd room from east located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	509	13212434 6565482 Original	§ 27-2005 adm code properly secure the loose faucet at sink in the kitchen located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	501	13212435 6565482 Original	§ 27-2005 adm code properly repair the broken or defective rotten wood floor at base cabinet in the kitchen located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26

1F 3	2019/08/06 2019/08/08	B	506	13212437 6565482 Original	§ 27-2005 adm code replace with new the missing electrical outlet cover at west wall in the kitchen located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	509	13212438 6565482 Original	§ 27-2005 adm code properly secure the loose wash basin in the bathroom located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	506	13212439 6565482 Original	§ 27-2005 adm code replace with new the missing base cabinet door at east wall in the kitchen located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	689	13212440 6565482 Original	§ 27-2005, 2006, 2037 hmc: properly repair and abate unsafe electric wiring condition consisting of exposed electrical wire at west wall in the kitchen located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	501	13212441 6565482 Original	§ 27-2005 adm code properly repair the broken or defective unhinged door at west wall in the entrance located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	508	13212444 6565482 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color at west wall in the 1st room from east located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	A	550	13212445 6565485 Original	§ 27-2017.3 hmc: trace and repair the source and abate the visible mold condition... approx. 4 sq ft at south wall in the bathroom located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOI SENT 2019/08/08	2019/11/25
1F 3	2019/08/06 2019/08/08	B	508	13212447 6565482 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color at east wall, south wall in the bathroom located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	501	13212619 6565482 Original	§ 27-2005 adm code properly repair the broken or defective electrical light fixture at ceiling in the bathroom located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	501	13212622 6565482 Original	§ 27-2005 adm code properly repair the broken or defective electrical light fixture at ceiling in the 1st room from east located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	501	13212624 6565482 Original	§ 27-2005 adm code properly repair the broken or defective electrical light fixture at ceiling in the 3rd room from east located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	501	13212630 6565482 Original	§ 27-2005 adm code properly repair the broken or defective electrical light fixture at ceiling in the kitchen located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
1F 3	2019/08/06 2019/08/08	B	501	13212635 6565482 Original	§ 27-2005 adm code properly repair the broken or defective electrical light fixture at ceiling in the foyer located at apt 1f, 3rd story, 1st apartment from north at east , section "south"	NOV SENT 2019/08/08	2019/09/26
Fire Escape	2019/08/06 2019/08/08	B	539	13212776 6565482 Original	§ 27-2005, 2007 adm code and dept. rules and regulations. remove the encumbrance obstructing egress from fire escapes consisting of household items and flower pots at 3rd, 4th, and 6th story balcony, the 2nd stack from south at west at building front	NOV SENT 2019/08/08	2019/09/26
A 2	2019/08/02 2019/08/07	C	550	13213769 6564849 Original	§ 27-2017.3 hmc: trace and repair the source and abate the visible mold condition... at ceiling and all walls approximately 20 sq. ft. in the bathroom located at apt a, 2nd story, 2nd apartment from north at east , section at north original violation 13096634 issued 29-may-19 has been upgraded to class c per administrative code §27-2017.3a(5)(a) or (b).	NOT COMPLIED 2019/09/20	2019/09/02
A 2	2019/08/02 2019/08/07	A	556	13207579 6563811 Original	§ 27-2013 adm code paint with light colored paint to the satisfaction of this department at ceiling and all walls in the bathroom located at apt a, 2nd story, 2nd apartment from west at north	NOV SENT 2019/08/07	2019/11/24
A 2	2019/08/02 2019/08/07	A	550	13207580 6563812 Original	§ 27-2017.3 hmc: trace and repair the source and abate the visible mold condition... aprx 6 saqa feet at ceiling and walls in the bathroom located at apt a, 2nd story, 2nd apartment from west at north	NOI SENT 2019/08/07	2019/11/24
A 2	2019/08/02 2019/08/07	C	530	13207581 6563813 Original	§ 27-2005, 2007 adm code arrange and make self-closing the doors .. in the entrance located at apt a, 2nd story, 2nd apartment from west at north	OPEN 2019/09/19	2019/09/02

1B 3	2019/07/19 2019/07/23	A	556	13185453 6548788 Original	§ 27-2013 adm code paint with light colored paint to the satisfaction of this department all peeling paint surfaces in the kitchen , the foyer , the 2nd room from east, the private hallway , the 1st room from east at north, the 1st room from east at south, the bathroom located at apt 1b, 3rd story, 1st apartment from north at east , section "north"	1 NO ACCESS 2019/09/11	2019/11/09
F 2	2019/07/19 2019/07/23	C	790	13182827 6548795 Original	§ 27-2043.1 hmc install the missing or repair/replace the defective window guard(s) in accordance with the specifications of the new york city health code section 24 rcny chapter 12. wg to install = 2; wg to replace = 0; wg to repair = 0; in the entire apartment located at apt f, 2nd story, 1st apartment from north at east , section "south"	NOT COMPLIED 2019/09/20	2019/08/25
F 2	2019/07/19 2019/07/23	B	510	13182828 6548794 Original	§ 27-2005 adm code & 309 m/d law abate the nuisance consisting of slide bolt with eye capable of padlock in the entrance located at apt f, 2nd story, 1st apartment from north at east , section "south"	1 NO ACCESS 2019/09/11	2019/09/10
F 2	2019/07/19 2019/07/23	B	508	13182829 6548794 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color at ceiling in the kitchen located at apt f, 2nd story, 1st apartment from north at east , section "south"	1 NO ACCESS 2019/09/11	2019/09/10
F 2	2019/07/19 2019/07/23	A	556	13182830 6548793 Original	§ 27-2013 adm code paint with light colored paint to the satisfaction of this department at north wall in the 2nd room from east located at apt f, 2nd story, 1st apartment from north at east , section "south"	1 NO ACCESS 2019/09/11	2019/11/09
1B 3	2019/07/19 2019/07/23	B	538 *	13182832 6548789 Original	§ 27-2005, 2007 adm code remove all encumbrances consisting of household items blocking second means of egress in the 1st room from east at south located at apt 1b, 3rd story, 1st apartment from north at east , section "north"	1 NO ACCESS 2019/09/11	2019/09/10
1B 3	2019/07/19 2019/07/23	B	1503	13182834 6548789 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s). inoperable in the entire apartment located at apt 1b, 3rd story, 1st apartment from north at east , section "north"	1 NO ACCESS 2019/09/11	2019/09/10
1B 3	2019/07/19 2019/07/23	B	702	13182835 6548789 Original	§ 27-2045 adm code repair or replace the smoke detector inoperable in the entire apartment located at apt 1b, 3rd story, 1st apartment from north at east , section "north"	1 NO ACCESS 2019/09/11	2019/09/10
1B 3	2019/07/19 2019/07/23	C	569	13182836 6548792 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of mice in the entire apartment located at apt 1b, 3rd story, 1st apartment from north at east , section "north"	DEFECT LETTER 2019/09/29	2019/08/18
1B 3	2019/07/19 2019/07/23	C	568	13182837 6548792 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of roaches in the entire apartment located at apt 1b, 3rd story, 1st apartment from north at east , section "north"	DEFECT LETTER 2019/09/29	2019/08/18
1B 3	2019/07/19 2019/07/23	A	550	13182838 6548791 Original	§ 27-2017.3 hmc: trace and repair the source and abate the visible mold condition... approx. 6 sq. ft at north wall in the bathroom located at apt 1b, 3rd story, 1st apartment from north at east , section "north"	1 NO ACCESS 2019/09/11	2019/11/09
1B 3	2019/07/19 2019/07/23	B	508	13182839 6548789 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color at north wall, ceiling in the bathroom located at apt 1b, 3rd story, 1st apartment from north at east , section "north"	1 NO ACCESS 2019/09/11	2019/09/10
3A 4	2019/06/14 2019/06/17	B	502	13125551 6513276 Original	§ 27-2005 adm code properly repair with similar material the broken or defective warped wood floor in the kitchen located at apt 3a, 4th story, 2nd apartment from north at east	NOT COMPLIED 2019/09/04	2019/08/05
3A 4	2019/06/14 2019/06/17	A	501	13125555 6513275 Original	§ 27-2005 adm code properly repair the broken or defective window spring balance, lower sash in the kitchen located at apt 3a, 4th story, 2nd apartment from north at east	NOT COMPLIED 2019/09/04	2019/10/04
3A 4	2019/06/14 2019/06/17	C	568	13125559 6513277 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of roaches in the entire apartment located at apt 3a, 4th story, 2nd apartment from north at east	NOT COMPLIED 2019/09/26	2019/07/13
2C 4	2019/05/29 2019/06/03	A	506	13096342 6499223 Original	§ 27-2005 adm code replace with new the missing escutcheon plate at riser in the bathroom located at apt 2c, 4th story, 1st apartment from west at north , section at north	NOT COMPLIED 2019/09/04	2019/09/20
4I 6	2019/05/29 2019/06/03	B	583	13096612 6499216 Original	§ 27-2026, 2027 hmc: properly repair the source and abate the evidence of a water leak at ceiling in the 4th room from east at south located at apt 4i, 6th story, 1st apartment from south at west , section at south	NOT COMPLIED 2019/09/20	2019/07/22




4I 6	2019/05/29 2019/06/03	A	508	13096616 6499215 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color the ceiling in the 4th room from east at south located at apt 4i, 6th story, 1st apartment from south at west , section at south	NOT COMPLIED 2019/09/11	2019/09/20
A 2	2019/05/29 2019/06/03	B	502	13096631 6499220 Original	§ 27-2005 adm code properly repair with similar material the broken or defective wood floor in the 3rd room from east located at apt a, 2nd story, 2nd apartment from north at east , section at north	NOT COMPLIED 2019/09/04	2019/07/22
A 2	2019/05/29 2019/06/03	B	508	13096635 6499220 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color at ceiling and all walls in the bathroom located at apt a, 2nd story, 2nd apartment from north at east , section at north	NOT COMPLIED 2019/09/04	2019/07/22
A 2	2019/05/29 2019/06/03	C	569	13096639 6499222 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of mice in the entire apartment located at apt a, 2nd story, 2nd apartment from north at east , section at north	NOT COMPLIED 2019/09/20	2019/06/29
2B 2	2019/05/28 2019/05/31	C	510	13094960 6496878 Original	§ 27-2005 adm code & 309 m/d law abate the nuisance consisting of slide and bolt and eye capable of being padlocked in the entrance located at apt 2b, 2nd story, 1st apartment from north at east	NOT COMPLIED 2019/09/20	2019/06/13
3B 3	2019/05/28 2019/05/31	B	1503	13095009 6496879 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s), missing in the entire apartment located at apt 3b, 3rd story, 1st apartment from north at east	CIV10 MAILED 2019/09/05	2019/07/19 2019/07/18
3B 3	2019/05/28 2019/05/31	B	702	13095011 6496879 Original	§ 27-2045 adm code repair or replace the smoke detector missing in the entire apartment located at apt 3b, 3rd story, 1st apartment from north at east	CIV10 MAILED 2019/09/05	2019/07/19 2019/07/18
2B 4	2019/05/24 2019/05/28	B	1503	13089876 6493850 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s), defective located at apt 2b, 4th story, 1st apartment from north at east , section at north	1 NO ACCESS 2019/09/11	2019/07/16
2B 4	2019/05/24 2019/05/28	B	702	13089878 6493850 Original	§ 27-2045 adm code repair or replace the smoke detector defective located at apt 2b, 4th story, 1st apartment from north at east , section at north	1 NO ACCESS 2019/09/11	2019/07/16
2B 4	2019/05/24 2019/05/28	A	579	13089901 6493849 Original	§ 27-2026 adm code repair the leaky and/or defective faucets at wash basin in the bathroom located at apt 2b, 4th story, 1st apartment from north at east , section at north	1 NO ACCESS 2019/09/11	2019/09/14
2B 4	2019/05/24 2019/05/28	C	510	13089903 6493851 Original	§ 27-2005 adm code & 309 m/d law abate the nuisance consisting of lockable lockset installed on room door leading to fire escape in the 1st room from east at south located at apt 2b, 4th story, 1st apartment from north at east , section at north	NOT COMPLIED 2019/09/20	2019/06/10
2J 4	2019/05/20 2019/05/22	B	510	13079887 6488382 Original	§ 27-2005 adm code & 309 m/d law abate the nuisance consisting of key operated lock at door leading to fire escape window located at apt 2j, 4th story, 1st apartment from west at north , section at south	NOT COMPLIED 2019/09/04	2019/07/10
2J 4	2019/05/20 2019/05/22	B	1503	13079889 6488382 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s), defective located at apt 2j, 4th story, 1st apartment from west at north , section at south	NOT COMPLIED 2019/09/04	2019/07/10
2J 4	2019/05/20 2019/05/22	B	702	13079892 6488382 Original	§ 27-2045 adm code repair or replace the smoke detector defective located at apt 2j, 4th story, 1st apartment from west at north , section at south	NOT COMPLIED 2019/09/04	2019/07/10
F 2	2019/05/20 2019/05/22	B	530	13079908 6488383 Original	§ 27-2005, 2007 adm code arrange and make self-closing the doors ... in the entrance located at apt f, 2nd story, 1st apartment from north at east , section at south	1 NO ACCESS 2019/09/11	2019/07/10
All Stories	2019/04/29 2019/05/01	B	501	13042569 6467527 Original	§ 27-2005 adm code properly repair the broken or defective heavy dutylock and locking assembly at entrance door at lobby	NOT COMPLIED 2019/09/04	2019/06/19
2H 4	2019/04/04 2019/04/09	B	505	13000820 6445781 Original	§ 27-2005 adm code replace with new the broken or defective ... broken glass at lower sash window in the kitchen located at apt 2h, 4th story, 1st apartment from south at west	1 NO ACCESS 2019/09/11	2019/05/28
2H 4	2019/04/04 2019/04/09	B	688	13000828 6445781 Original	§ 27-2037, 2038 hmc: provide a safe and adequate supply of electric service to the fixtures ... at east wall outlet in the 1st room from north located at apt 2h, 4th story, 1st apartment from south at west	1 NO ACCESS 2019/09/11	2019/05/28
2H 4	2019/04/04 2019/04/09	B	688	13000832 6445781 Original	§ 27-2037, 2038 hmc: provide a safe and adequate supply of electric service to the fixtures ... south wall light switch in the 1st room from north located at apt 2h, 4th story, 1st apartment from south at west	1 NO ACCESS 2019/09/11	2019/05/28
2H 4	2019/04/04 2019/04/09	B	510	13000842 6445781 Original	§ 27-2005 adm code & 309 m/d law abate the nuisance consisting of ... key operated lock at door restricting egress to fire escape in the 1st room from north located at apt 2h, 4th story, 1st apartment from south at	1 NO ACCESS 2019/09/11	2019/05/28

west							
2H 4	2019/04/04 2019/04/09	B	577 *	13000845 6445781 Original	§ 27-2024 adm code provide adequate supply of hot water for the fixtures ... at wash basin in the bathroom located at apt 2h, 4th story, 1st apartment from south at west	1 NO ACCESS 2019/09/11	2019/05/28
2H 4	2019/04/04 2019/04/09	B	502	13000849 6445781 Original	§ 27-2005 adm code properly repair with similar material the broken or defective ... wood floor by radiator in the 3rd room from north at west located at apt 2h, 4th story, 1st apartment from south at west	1 NO ACCESS 2019/09/11	2019/05/28
2H 4	2019/04/04 2019/04/09	B	598	13000855 6445781 Original	§ 27-2026 adm code repair the broken or defective connection ... at radiator shut off valve in the 3rd room from north at west located at apt 2h, 4th story, 1st apartment from south at west	1 NO ACCESS 2019/09/29	2019/05/28
2H 4	2019/04/04 2019/04/09	B	688	13000860 6445781 Original	§ 27-2037, 2038 hmc: provide a safe and adequate supply of electric service to the fixtures ... at west wall outlet in the 3rd room from north at west located at apt 2h, 4th story, 1st apartment from south at west	1 NO ACCESS 2019/09/11	2019/05/28
2H 4	2019/04/04 2019/04/09	A	491	13000887 6445780 Original	§ 300 m/d law file plans and application and legalize the following alteration or restore to the legal condition existing prior to the making of said alteration ... east wall erected with sheetrock and stud in the 3rd room from north at west located at apt 2h, 4th story, 1st apartment from south at west	1 NO ACCESS 2019/09/11	2019/07/27
2H 4	2019/04/04 2019/04/09	B	688	13000889 6445781 Original	§ 27-2037, 2038 hmc: provide a safe and adequate supply of electric service to the fixtures ... at east wall outlet in the 3rd room from north at east located at apt 2h, 4th story, 1st apartment from south at west	1 NO ACCESS 2019/09/11	2019/05/28
2H 4	2019/04/04 2019/04/09	B	505	13000892 6445781 Original	§ 27-2005 adm code replace with new the broken or defective ... marble saddle in the entrance located at apt 2h, 4th story, 1st apartment from south at west	1 NO ACCESS 2019/09/11	2019/05/28
2H 4	2019/04/04 2019/04/09	C	569	13000907 6445783 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of mice in the entire apartment located at apt 2h, 4th story, 1st apartment from south at west	1 NO ACCESS 2019/09/29	2019/05/05
2H 4	2019/04/04 2019/04/09	C	790	13000908 6445782 Original	§ 27-2043.1 hmc install the missing or repair/replace the defective window guard(s) in accordance with the specifications of the new york city health code section 24 rcny chapter 12. wg to install = 0; wg to replace = 1; wg to repair = 0; in the entire apartment located at apt 2h, 4th story, 1st apartment from south at west	1 NO ACCESS 2019/09/29	2019/05/12
2H 4	2019/04/04 2019/04/09	B	1503	13000910 6445781 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s). ... inoperable in the entire apartment located at apt 2h, 4th story, 1st apartment from south at west	1 NO ACCESS 2019/09/11	2019/05/28
2H 4	2019/04/04 2019/04/09	B	702	13000912 6445781 Original	§ 27-2045 adm code repair or replace the smoke detector ... inoperable in the entire apartment located at apt 2h, 4th story, 1st apartment from south at west	1 NO ACCESS 2019/09/11	2019/05/28
1	2019/04/04 2019/04/09	B	502	13000924 6445781 Original	§ 27-2005 adm code properly repair with similar material the broken or defective ... ceramic floor tile near building entry door at public hall, 1st story	NOT COMPLIED 2019/09/04	2019/05/28
Yards / Courts	2019/04/04 2019/04/09	B	502	13000930 6445781 Original	§ 27-2005 adm code properly repair with similar material the broken or defective ... concrete step, 5 steps up from bottom at stoop	NOT COMPLIED 2019/09/04	2019/05/28
2B 4	2019/04/04 2019/04/09	B	502	12999083 6445777 Original	§ 27-2005 adm code properly repair with similar material the broken or defective wood floor in the 1st room from east at north located at apt 2b, 4th story, 1st apartment from north at east	1 NO ACCESS 2019/09/11	2019/05/28
2B 4	2019/04/04 2019/04/09	B	502	12999087 6445777 Original	§ 27-2005 adm code properly repair with similar material the broken or defective wood floor in the 2nd room from east located at apt 2b, 4th story, 1st apartment from north at east	1 NO ACCESS 2019/09/11	2019/05/28
2B 4	2019/04/04 2019/04/09	C	568	12999088 6445778 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of roaches in the entire apartment located at apt 2b, 4th story, 1st apartment from north at east	NOT COMPLIED 2019/09/20	2019/05/05
2B 4	2019/04/04 2019/04/09	B	502	12999090 6445777 Original	§ 27-2005 adm code properly repair with similar material the broken or defective wood floor in the kitchen located at apt 2b, 4th story, 1st apartment from north at east	1 NO ACCESS 2019/09/11	2019/05/28
2B 4	2019/04/04 2019/04/09	B	505	12999094 6445777 Original	§ 27-2005 adm code replace with new the broken or defective wood door in the bathroom located at apt 2b, 4th story, 1st apartment from north at east	1 NO ACCESS 2019/09/11	2019/05/28
2B 4	2019/04/04 2019/04/09	B	598	12999097 6445777 Original	§ 27-2026 adm code repair the broken or defective connection wasteline at wash basin in the bathroom located at apt 2b, 4th story, 1st apartment from north at east	NOT COMPLIED 2019/09/20	2019/05/28
2B 4	2019/04/04 2019/04/09	B	702	12999099 6445777 Original	§ 27-2045 adm code repair or replace the smoke detector defective in the entire apartment located at apt 2b, 4th story, 1st apartment from north at east	1 NO ACCESS 2019/09/11	2019/05/28

2B 4	2019/04/04 2019/04/09	B	1503	12999101 6445777 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s). defective in the entire apartment located at apt 2b, 4th story, 1st apartment from north at east	1 NO ACCESS 2019/09/11	2019/05/28
2B 4	2019/04/04 2019/04/08	A	556	12999078 6443835 Original	§ 27-2013 adm code paint with light colored paint to the satisfaction of this department all walls and ceiling in the bathroom located at apt 2b, 4th story, 1st apartment from north at east	1 NO ACCESS 2019/09/11	2019/07/26
2B 4	2019/04/04 2019/04/08	B	502	12999081 6443836 Original	§ 27-2005 adm code properly repair with similar material the broken or defective wood floor in the 1st room from east at south located at apt 2b, 4th story, 1st apartment from north at east	1 NO ACCESS 2019/09/11	2019/05/27
3B 3	2019/03/21 2019/03/25	C	568	12973851 6429854 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of roaches in the entire apartment located at apt 3b, 3rd story, 1st apartment from north at east , section at north	NOT COMPLIED 2019/09/30	2019/04/20
3B 3	2019/03/21 2019/03/25	B	502	12973856 6429853 Original	§ 27-2005 adm code properly repair with similar material the broken or defective wood floor in the entire apartment located at apt 3b, 3rd story, 1st apartment from north at east , section at north	NOT COMPLIED 2019/09/04	2019/05/13
3B 3	2019/03/21 2019/03/25	B	505	12973896 6429853 Original	§ 27-2005 adm code replace with new the broken or defective east base cabinet in the kitchen located at apt 3b, 3rd story, 1st apartment from north at east , section at north	NOT COMPLIED 2019/09/04	2019/05/13
3B 3	2019/03/21 2019/03/25	C	567 *	12973899 6429854 Original	hmc adm code: § 27-2017.4 abate the infestation consisting of rodents rats in the entire apartment located at apt 3b, 3rd story, 1st apartment from north at east , section at north	NOT COMPLIED 2019/09/30	2019/04/20
3B 3	2019/03/21 2019/03/25	B	1503	12973903 6429853 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s). defective located at apt 3b, 3rd story, 1st apartment from north at east , section at north	NOT COMPLIED 2019/09/04	2019/05/13
3B 3	2019/03/21 2019/03/25	B	702	12973908 6429853 Original	§ 27-2045 adm code repair or replace the smoke detector defective located at apt 3b, 3rd story, 1st apartment from north at east , section at north	NOT COMPLIED 2019/09/04	2019/05/13
3I 3	2019/03/15 2019/03/18	B	501	12963263 6424236 Original	§ 27-2005 adm code properly repair the broken or defective intercom at south wall in the private hallway located at apt 3i, 3rd story, 1st apartment from south at west , section "south"	NOT COMPLIED 2019/09/04	2019/05/06
F 1	2019/03/15 2019/03/18	B	530	12963334 6424235 Original	§ 27-2005, 2007 adm code arrange and make self-closing the doors at apt entrance located at apt f, 1st story, 3rd apartment from north at east , section "south"	1 NO ACCESS 2019/09/11	2019/05/06
All Stories	2019/02/08 2019/02/15	B	502	12901166 6394566 Original	§ 27-2005 adm code properly repair with similar material the broken or defective rotting wood base at skylight at the bulk head.	NOT COMPLIED 2019/09/04	2019/04/05
All Stories	2019/02/08 2019/02/15	B	502	12901167 6394566 Original	§ 27-2005 adm code properly repair with similar material the broken or defective fire rated material at the north south and east walls at the bulk head	NOT COMPLIED 2019/09/04	2019/04/05
6	2019/02/06 2019/02/13	A	556	12896288 6392130 Original	§ 27-2013 adm code paint with light colored paint to the satisfaction of this department the north wall at public hall, 6th story	NOT COMPLIED 2019/09/04	2019/06/02
1F 2	2019/02/06 2019/02/11	B	530	12897328 6389560 Original	§ 27-2005, 2007 adm code arrange and make self-closing the doors ... in the entrance located at apt 1f, 2nd story, 1st apartment from north at east	NOT COMPLIED 2019/09/04	2019/04/01
1F 2	2019/02/06 2019/02/11	C	568	12897330 6389561 Original	§ 27-2018 admin. code: abate the nuisance consisting of roaches in the entire apartment located at apt 1f, 2nd story, 1st apartment from north at east	DEFECT LETTER 2019/09/29	2019/03/09
1F 2	2019/02/06 2019/02/11	C	569	12897333 6389561 Original	§ 27-2018 admin. code: abate the nuisance consisting of mice in the entire apartment located at apt 1f, 2nd story, 1st apartment from north at east	DEFECT LETTER 2019/09/29	2019/03/09
1F 2	2019/02/06 2019/02/11	B	502	12897334 6389560 Original	§ 27-2005 adm code properly repair with similar material the broken or defective wood floor in the entire apartment located at apt 1f, 2nd story, 1st apartment from north at east	NOT COMPLIED 2019/09/04	2019/04/01
3B 5	2019/01/16 2019/01/18	B	1503	12858316 6366196 Original	§ 27-2046.1 hmc: repair or replace the carbon monoxide detecting device(s). defective located at apt 3b, 5th story, 1st apartment from north at east , section at north	NOT COMPLIED 2019/09/04	2019/03/08
3B 5	2019/01/16 2019/01/18	B	702	12858317 6366196 Original	§ 27-2045 adm code repair or replace the smoke detector defective located at apt 3b, 5th story, 1st apartment from north at east , section at north	NOT COMPLIED 2019/09/04	2019/03/08
4C 4	2018/12/23 2018/12/27	A	529	12825272 6348188 Original	§ 27-2005 adm code refit upper and lower counter balances in the entire apartment located at apt 4c, 4th story, 1st apartment from west at north	NOT COMPLIED 2019/09/04	2019/04/15

F 2	2018/12/21 2018/12/26	B	530	12820133 6346566 Original	§ 27-2005, 2007 adm code arrange and make self-closing the doors . in the entrance located at apt f, 2nd story, 1st apartment from north at east	1 NO ACCESS 2019/09/11	2019/02/13
3H 5	2018/12/05 2018/12/07	B	501	12791084 6331151 Original	§ 27-2005 adm code properly repair the broken or defective spring balance at upper sash window in the 3rd room from east located at apt 3h, 5th story, 1st apartment from east at south , section at south	NOT COMPLIED 2019/09/04	2019/01/25
3H 5	2018/12/05 2018/12/07	B	510	12791087 6331151 Original	§ 27-2005 adm code & 309 m/d law abate the nuisance consisting of key operated lock at door leading to fire escape window located at apt 3h, 5th story, 1st apartment from east at south , section at south	NOT COMPLIED 2019/09/04	2019/01/25
3H 5	2018/12/05 2018/12/07	B	510	12791088 6331151 Original	§ 27-2005 adm code & 309 m/d law abate the nuisance consisting of air conditioner installed at fire escape window located at apt 3h, 5th story, 1st apartment from east at south , section at south	NOT COMPLIED 2019/09/04	2019/01/25
M Basement	2018/12/05 2018/12/07	B	502	12791515 6331153 Original	§ 27-2005 adm code properly repair with similar material the broken or defective wood floor in the entire apartment located at apt m, 1st apartment from north at east	NOT COMPLIED 2019/09/04	2019/01/25
4G 6	2018/09/12 2018/09/17	B	568	12582831 6193074 Original	§ 27-2018 admin. code: abate the nuisance consisting of roaches in the entire apartment located at apt 4g, 6th story, 2nd apartment from north at east	NOT COMPLIED 2019/09/04	2018/11/05
2B 2	2018/09/12 2018/09/17	B	508	12582863 6193075 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color the ceiling and walls in the bathroom located at apt 2b, 2nd story, 1st apartment from north at east	1 NO ACCESS 2019/09/11	2018/11/05
2B 2	2018/09/12 2018/09/17	B	550	12582866 6193076 Original	§ 27-2005 hmc:trace and repair the source and abate the nuisance consisting of mold ... at ceiling and wall approx 4 sq.ft in the bathroom located at apt 2b, 2nd story, 1st apartment from north at east	DEFECT LETTER 2019/09/20	2018/11/05
2B 2	2018/09/12 2018/09/17	B	502	12582868 6193075 Original	§ 27-2005 adm code properly repair with similar material the broken or defective rotten wOod floor in the entire apartment located at apt 2b, 2nd story, 1st apartment from north at east	1 NO ACCESS 2019/09/11	2018/11/05
2B 2	2018/09/12 2018/09/17	B	598	12582874 6193075 Original	§ 27-2026 adm code repair the broken or defective connection wash basin drain in the bathroom located at apt 2b, 2nd story, 1st apartment from north at east	NOT COMPLIED 2019/09/20	2018/11/05
N 1	2018/09/12 2018/09/17	B	502	12582883 6193078 Original	§ 27-2005 adm code properly repair with similar material the broken or defective rotten wood floor in the entire apartment located at apt n, 1st story, 1st apartment from south at west , section "nouth "	1 NO ACCESS 2019/09/11	2018/11/05
N 1	2018/09/12 2018/09/17	B	508	12582887 6193078 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color the ceiling and wall in the bathroom located at apt n, 1st story, 1st apartment from south at west , section "nouth "	1 NO ACCESS 2019/09/11	2018/11/05
N 1	2018/09/12 2018/09/17	B	550	12582891 6193079 Original	§ 27-2005 hmc:trace and repair the source and abate the nuisance consisting of mold ... at ceiling approx 3 sq.ft in the 1st room from east at north located at apt n, 1st story, 1st apartment from south at west , section "nouth "	1 NO ACCESS 2019/09/29	2018/11/05
N 1	2018/09/12 2018/09/17	B	569	12582895 6193078 Original	§ 27-2018 admin. code: abate the nuisance consisting of mice in the entire apartment located at apt n, 1st story, 1st apartment from south at west , section "nouth "	1 NO ACCESS 2019/09/11	2018/11/05
3I 5	2018/09/05 2018/09/10	B	526 *	12566834 6186010 Original	§ 27-2005, 2007 adm code remove the illegal fastening key operated lock installed at door leading to fire escape in the 3rd room from east at south located at apt 3i, 5th story, 1st apartment from north at east	NOT COMPLIED 2019/09/04	2018/10/29
3B 5	2018/07/25 2018/07/27	B	568	12495958 6150123 Original	§ 27-2018 admin. code: abate the nuisance consisting of roaches located at apt 3b, 5th story, 1st apartment from north at east	NOT COMPLIED 2019/09/04	2018/09/14
3B 5	2018/07/25 2018/07/27	B	569	12495965 6150123 Original	§ 27-2018 admin. code: abate the nuisance consisting of mice located at apt 3b, 5th story, 1st apartment from north at east	NOT COMPLIED 2019/09/04	2018/09/14
3B 5	2018/07/25 2018/07/27	B	702	12495970 6150123 Original	§ 27-2045 adm code repair or replace the smoke detector defective located at apt 3b, 5th story, 1st apartment from north at east	NOT COMPLIED 2019/09/04	2018/09/14
3B 5	2018/07/25 2018/07/27	B	1502	12495973 6150123 Original	§ 27-2046.1, 2046.2 hmc: provide an approved and operational carbon monoxide detecting device, installed in accordance with applicable law and rules. located at apt 3b, 5th story, 1st apartment from north at east	NOT COMPLIED 2019/09/04	2018/09/14
1E 2	2018/03/06 2018/03/08	B	550	12275677 6034370 Original	§ 27-2005 hmc:trace and repair the source and abate the nuisance consisting of mold ... and mildew at ceiling approx 15 sq feet in the bathroom located at apt 1e, 2nd story, 1st apartment from east at south	DEFECT LETTER 2019/09/29	2018/04/26
1E 2	2018/03/06 2018/03/08	B	502	12275684 6034369 Original	§ 27-2005 adm code properly repair with similar material the broken or defective cracked wood floor in the kitchen located at apt 1e, 2nd story, 1st apartment from east at south	1 NO ACCESS 2019/09/11	2018/04/26

1E 3	2018/03/06 2018/03/08	B	569	12275693 6034369 Original	§ 27-2018 admin. code: abate the nuisance consisting of mice in the entire apartment located at apt 1e, 3rd story, 1st apartment from east at south	1 NO ACCESS 2019/09/11	2018/04/26
1E 3	2018/03/06 2018/03/08	B	568	12275698 6034369 Original	§ 27-2018 admin. code: abate the nuisance consisting of roaches in the entire apartment located at apt 1e, 3rd story, 1st apartment from east at south	1 NO ACCESS 2019/09/11	2018/04/26
1E 3	2018/03/06 2018/03/08	B	501	12275701 6034369 Original	§ 27-2005 adm code properly repair the broken or defective assembly lock at door in the entrance located at apt 1e, 3rd story, 1st apartment from east at south	1 NO ACCESS 2019/09/11	2018/04/26
2J 3	2018/03/06 2018/03/08	B	508	12275727 6034371 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color at ceiling in the bathroom located at apt 2j, 3rd story, 1st apartment from west at north	NOT COMPLIED 2019/09/04	2018/04/26
2J 3	2018/01/26 2018/01/30	A	556	12215442 6003503 Original	§ 27-2013 adm code paint with light colored paint to the satisfaction of this department all peeling paint surfaces in the bathroom , the private hallway , the kitchen , the foyer , the 2nd room from east located at apt 2j, 3rd story, 1st apartment from west at north	NOT COMPLIED 2019/09/04	2018/05/19
1E 3	2017/11/16 2017/11/20	B	502	12078805 5913104 Original	§ 27-2005 adm code properly repair with similar material the broken or defective cracking and warped wood floor in the kitchen located at apt 1e, 3rd story, 1st apartment from north at east , section at north	1 NO ACCESS 2019/09/11	2018/01/08
1E 3	2017/11/16 2017/11/20	B	569	12078806 5913104 Original	§ 27-2018 admin. code: abate the nuisance consisting of mice in the entire apartment located at apt 1e, 3rd story, 1st apartment from north at east , section at north	1 NO ACCESS 2019/09/11	2018/01/08
1E 3	2017/11/16 2017/11/20	B	568	12078807 5913104 Original	§ 27-2018 admin. code: abate the nuisance consisting of roaches in the entire apartment located at apt 1e, 3rd story, 1st apartment from north at east , section at north	1 NO ACCESS 2019/09/11	2018/01/08
1E 3	2017/11/16 2017/11/20	B	509	12078808 5913104 Original	§ 27-2005 adm code properly secure the loose mortice lock and it's assembly at door in the entrance located at apt 1e, 3rd story, 1st apartment from north at east , section at north	1 NO ACCESS 2019/09/11	2018/01/08
4F 5	2017/04/05 2017/04/07	B	508	11722521 5722196 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color at ceiling in the 1st room from north located at apt 4f, 5th story, 1st apartment from east at south	1 NO ACCESS 2019/09/11	2017/05/26
4F 5	2017/04/05 2017/04/07	B	505	11722529 5722196 Original	§ 27-2005 adm code replace with new the broken or defective handle of the body of the shower in the bathroom located at apt 4f, 5th story, 1st apartment from east at south	1 NO ACCESS 2019/09/11	2017/05/26
4F 5	2017/04/05 2017/04/07	B	508	11722535 5722196 Original	§ 27-2005 adm code repair the broken or defective plastered surfaces and paint in a uniform color north and south wall in the bathroom located at apt 4f, 5th story, 1st apartment from east at south	1 NO ACCESS 2019/09/11	2017/05/26
1J 3	2016/06/29 2016/07/11	C	616	11304097 5468188 Original	§ 27-2056.6 adm code - correct the lead-based paint hazard - presumed lead paint that is peeling or on a deteriorated subsurface using work practices set forth in 28 rcny §11-06(b)(2) ceiling in the bathroom located at apt 1j, 3rd story, 1st apartment from west at north , section at south	DEFECT LETTER 2019/09/29	2016/08/13
	2016/06/29 2016/07/01	B	658	11293564 5463348 Original	§ 27-2005 adm code properly repair the broken or defective paving at rear yard	NOT COMPLIED 2019/09/05	2016/08/19
2B 2	2015/12/22 2015/12/24	B	568	11046889 5331854 Original	§ 27-2018 admin. code: abate the nuisance consisting of roaches in the entire apartment located at apt 2b, 2nd story, 1st apartment from north at east	1 NO ACCESS 2019/09/11	2016/02/11
1A 2	2015/03/19 2015/03/24	A	491	10637999 5079750 Original	§ 300 m/d law file plans and application and legalize the following alteration or restore to the legal condition existing prior to the making of said alteration sheet rock partition wall erected from the floor to the ceiling creating additional room in the 3rd room from east located at apt 1a, 2nd story, 2nd apartment from north at east	NOT COMPLIED 2019/09/11	2015/07/11
2D 4	2015/01/12 2015/01/20	C	616	10510453 4985992 Original	§ 27-2056.6 adm code - correct the lead-based paint hazard - presumed lead paint that is peeling or on a deteriorated subsurface using work practices set forth in 28 rcny §11-06(b)(2) south wall, east wall in the 2nd room from east at north located at apt 2d, 4th story, 1st apartment from south at west , section at north	DEFECT LETTER 2019/09/21	2015/02/22
4H 6	2012/03/08 2012/03/12	B	505	9358784 4372889 Original	§ 27-2005 adm code replace with new the broken or defective closet door in the 5th room from east located at apt 4h, 6th story, apartment at south , section at south	1 NO ACCESS 2019/09/11	2012/04/30 2012/06/12
	2019/10/30 -	I	730	13389922	§ 27-2091(c) adm code the property has been issued an order to identify and address underlying conditions and violations related to the order. failure to comply may result in extensive repair work to correct underlying conditions and related violations by hpd.	INFO NOV SENT 2019/10/31	-



charges for repair work done pursuant to this order, if not paid, will become tax liens on the property



[Services](#) | [News & Features](#) | [City Life](#) | [City Agencies](#) | [Office of the Mayor](#) | [Contact Us](#) | [Search](#)

NYC.gov - NEW YORK CITY'S OFFICIAL WEB SITE