

The selected address: **3569 DEKALB AVENUE, Bronx 10467**

This building has filed records with the [New York State Division of Housing and Community Renewal](#) at least one time from 1993 to the present year and may contain one or more regulated apartments.

HPD#	Range	Block	Lot	CD	CensusTract	Stories	A Units	B Units	Ownership	Registration#	Class
61064	Active	3569-3569	03329	0040	7 43100	6	54	0	PVT	200894	B

- Other Units
- Property Owner Registration Information
- Charges
- Completed Status
- Complaint History
- Litigation/Cases Status
- Tenant Harassment Report
- All Open Violations
- prior year Open Viol's
- Escortation
- Overdue Lead Paint Viol Correction
- Vacate Orders
- L-Card Issues
- PROS Orders
- Bed Bugs
- Mold

Complaint History

Historial de Quejas

Complaints received by the Department of Housing Preservation and Development within the last year are listed below. Note: One complaint # may have multiple complaint conditions associated with it.

If you require information regarding a complaint older than 1 year, you may contact HPD at any of the [Borough Office locations](#) to request a copy. There may be a fee for any requested copies.

TENANTS: If your landlord does not correct the condition(s), you have the right to initiate a tenant action against him/her in Housing Court. The Court has the authority to order the landlord to correct the condition(s) and can assess penalties for failure to comply. There is a \$45 fee to file, which the Court may waive if you are unable to pay. For further information on the court process, you can call the Citywide Task Force on Housing Court at 212-962-4795, weekdays between 2 PM and 5PM.

LANDLORDS: Take immediate action to correct the conditions cited below. Failure to comply may result in the issuance of a violation and/or Housing Court action.

*** Apartment # ANON means that the complaint was filed anonymously ***

Find Apartment#

Complaint Date	Complaint #	SR#	Apt#	Complaint Condition	Condition Detail	Location
11/01/2019	9832667	311-01022609	3J	WINDOW FRAME	LOCK BRKN/MISS	ENTIRE APT
11/01/2019	9832667	311-01022609	3J	OUTLET/SWITCH	OUTLET DEFECT	BATHROOM
11/01/2019	9832667	311-01022609	3J	WINDOW FRAME	WINDOW STUCK	ENTIRE APT
11/01/2019	9832667	311-01022609	3J	PESTS	MICE	ENTIRE APT
11/01/2019	9832647	311-01022460	3J	ELEC/GAS-RANGE	PILOT LIGHT INO	KITCHEN
11/01/2019	9832647	311-01022460	3J	LIGHTING	FIXT MISS/HANG	BATHROOM
11/01/2019	9832647	311-01022460	3J	OUTLET/SWITCH	OUTLET DEFECT	BATHROOM
11/01/2019	9832647	311-01022460	3J	WINDOW FRAME	WINDOW STUCK	ENTIRE APT
11/01/2019	9832647	311-01022460	3J	BATHTUB	NO WATER	BATHROOM
11/01/2019	9832647	311-01022460	3J	PESTS	MICE	ENTIRE APT
10/16/2019	9766102	311-00884787	MBASEM WALLS	PEELING	PEELING	ENTIRE APT
10/16/2019	9766079	311-00884572	MBASEM CEILING	COLLAPSING	COLLAPSING	KITCHEN
10/16/2019	9766079	311-00884572	MBASEM PESTS	OTHER	OTHER	ENTIRE APT
10/16/2019	9766079	311-00884572	MBASEM MOLD	N/A	N/A	ENTIRE APT
10/16/2019	9766079	311-00884572	MBASEM PESTS	MICE	MICE	ENTIRE APT
10/16/2019	9766079	311-00884572	MBASEM FLOOR	SAGGING/SLOPING	SAGGING/SLOPING	BEDROOM
10/16/2019	9766079	311-00884572	MBASEM WALLS	PAINT DIRTY	PAINT DIRTY	BEDROOM
10/08/2019	9757940	311-00828665	2D	MOLD	N/A	BATHROOM
10/07/2019	9756586	311-00818851	F	PESTS	BED BUGS	ENTIRE APT
09/30/2019	9742817	311-00761189	2D	MOLD	N/A	ENTIRE APT
09/25/2019	9739406	311-00722149	1C	NOLIGHTING	ONE ROOM/AREA	PUBLIC HALL
09/23/2019	9737420	311-00705732	3F	DOOR	BRKN / MISSING	ENTIRE APT
09/23/2019	9737405	311-00705432	3F	STEAMPIPE/RISR	CRACKED/BRKN	LIVING ROOM
09/23/2019	9737405	311-00705432	3F	SLOWLEAK	AT WALL/CEIL	LIVING ROOM
09/23/2019	9737405	311-00705432	3F	CEILING	CRACKED	LIVING ROOM
08/29/2019	9715795	311-00498853	A	PESTS	MICE	ENTIRE APT
08/29/2019	9715795	311-00498853	A	BASIN/SINK	MISSING	KITCHEN
08/29/2019	9715795	311-00498853	A	WALLS	PEELING	ENTIRE APT
08/29/2019	9715795	311-00498853	A	FLOOR	HOLE WALK AREA	ENTIRE APT
08/20/2019	9708015	311-00423348	G	ENTIREBUILDING	NO HOT WATER	BUILDING-WIDE
08/19/2019	9706920	311-00414966	4I	ENTIREBUILDING	NO HOT WATER	BUILDING-WIDE
08/19/2019	9706835	311-00414409	ANON	DOOR	NEED KEY EXIT	BLDG ENTRANCE
08/19/2019	9706834	311-00414386	ANON	WATER-SUPPLY	NO-HOT- WATER	BUILDING-WIDE
08/18/2019	9706626	311-00410987	2I	APARTMENTONLY	NO HOT WATER	ENTIRE APT
08/16/2019	9705097	311-00392032	2C	STAIRS	STEP BRKN	STAIRS
08/16/2019	9705097	311-00392032	2C	DOOR	BRKN / MISSING	OTHER
08/16/2019	9705097	311-00392032	2C	WATER-SUPPLY	NO-HOT- WATER	COMMUNITY BTHRM

08/16/2019	9705097	311-00392032	2C	GBG/RCYCLNG STG	ACCUMULATION	PUBLIC HALL
08/07/2019	9696089	311-00324872	I	WINDOW PANE	GLASS BRKN/MISS	BEDROOM
08/07/2019	9696089	311-00324872	I	BATHTUB	CHIPPING/ERODE	BATHROOM
08/07/2019	9696089	311-00324872	I	FLOOR	SAGGING/SLOPING	LIVING ROOM
08/07/2019	9696089	311-00324872	I	CABINETS	PEELING PAINT	KITCHEN
08/07/2019	9696089	311-00324872	I	WINDOW FRAME	LOOSE/DEFECTIVE	BATHROOM
08/07/2019	9696089	311-00324872	I	FLOOR	TILE BRKN/MISS	BATHROOM
08/07/2019	9696077	311-00324804	I	FLOOR	SAGGING/SLOPING	BEDROOM
08/06/2019	9694676	311-00313744	F	GBG/RCYCLNG STG	ACCUMULATION	BLDG ENTRANCE
08/05/2019	9693978	311-00307106	3I	MOLD	N/A	LIVING ROOM
08/05/2019	9693978	311-00307106	3I	BLL/BZZR/INTRCM	BRKN OR MISSING	ENTRANCE
08/04/2019	9693529	311-00301838	1F	FLOOR	FLR COVR DAMAGE	ENTIRE APT
08/04/2019	9693529	311-00301838	1F	DOOR FRAME	FRAME BROKEN	ENTRANCE
08/04/2019	9693529	311-00301838	1F	ELECTRIC-WIRING	EXPOSED	BATHROOM
08/04/2019	9693529	311-00301838	1F	WINDOW FRAME	LOOSE/DEFECTIVE	ENTIRE APT
08/04/2019	9693529	311-00301838	1F	MOLD	N/A	ENTIRE APT
08/04/2019	9693529	311-00301838	1F	CEILING	COLLAPSING	BATHROOM
08/04/2019	9693529	311-00301838	1F	BASIN/SINK	DETACHED	BATHROOM
08/04/2019	9693529	311-00301838	1F	OUTLET/SWITCH	OUTLET DEFECT	ENTIRE APT
08/04/2019	9693529	311-00301838	1F	CABINETS	DEFECTIVE	KITCHEN
07/29/2019	9688360	311-00250877	3I	MOLD	N/A	LIVING ROOM
07/22/2019	9683279	311-00198624	ANON	NOLIGHTING	ONE ROOM/AREA	STAIRS
07/17/2019	9676875	311-00156125	F	SLOWLEAK	AT WALL/CEIL	LIVING ROOM
07/17/2019	9676875	311-00156125	F	FLOOR	SAGGING/SLOPING	OTHER
07/17/2019	9676865	311-00156006	F	MOLD	N/A	ENTIRE APT
07/10/2019	9670697	311-00095125	1B	WALLS	PEELING	BATHROOM
06/12/2019	9647473	1-1-1734853912	3A	FLOOR	SAGGING/SLOPING	KITCHEN
06/12/2019	9647473	1-1-1734853912	3A	WINDOW FRAME	WINDOW STUCK	ENTIRE APT
06/12/2019	9647473	1-1-1734853912	3A	SLOWLEAK	AT WALL/CEIL	ENTIRE APT
06/12/2019	9647473	1-1-1734853912	3A	WNGRDBRKN/MSG	CHILD UNDER 11	ENTIRE APT
05/15/2019	9621495	1-1-1721236592	2B	ELEC/GAS-RANGE	OVEN DOOR	KITCHEN
05/15/2019	9621495	1-1-1721236592	2B	REFRIGERATOR	BROKE DOOR SEAL	KITCHEN
05/15/2019	9621265	1-1-1721149232	2C	FLOOR	TILE BRKN/MISS	ENTIRE APT
05/15/2019	9621265	1-1-1721149232	2C	WALLS	TILE BRKN/MISS	BATHROOM
05/15/2019	9621265	1-1-1721149232	2C	WALLS	PEELING	ENTIRE APT
05/15/2019	9621265	1-1-1721149232	2C	REFRIGERATOR	BROKE DOOR SEAL	KITCHEN
05/15/2019	9621265	1-1-1721149232	2C	SMOKEDETECTOR	BRKN/MISSING	ENTIRE APT
05/15/2019	9621265	1-1-1721149232	2C	BASIN/SINK	FAUCET-BROKEN	KITCHEN
05/15/2019	9621265	1-1-1721149232	2C	FLOOR	SAGGING/SLOPING	ENTIRE APT
05/15/2019	9621265	1-1-1721149232	2C	CODETECTOR	BRKN/MISSING	ENTIRE APT
05/15/2019	9621265	1-1-1721149232	2C	DOOR	LOCK BRKN/MISS	ENTRANCE
05/15/2019	9621265	1-1-1721149232	2C	DOOR	BRKN / MISSING	BATHROOM
05/13/2019	9617859	1-1-1720192902	A	FLOOR	BRKN/DEFECTIVE	ENTIRE APT
04/29/2019	9604467	1-1-1714407392	F	PESTS	BED BUGS	ENTIRE APT
04/27/2019	9601968	1-1-1713539802	2I	APARTMENTONLY	NO HEAT	ENTIRE APT
04/24/2019	9596581	1-1-1712281962	4I	ELEC/GAS-RANGE	KNOBS MISS/BROK	KITCHEN
04/24/2019	9596581	1-1-1712281962	4I	SLOWLEAK	AT WALL/CEIL	BEDROOM
04/24/2019	9596581	1-1-1712281962	4I	FLOOR	FLR COVR DAMAGE	BEDROOM
04/24/2019	9596577	1-1-1712289532	3G	LIGHTING	DIMS	LIVING ROOM
04/24/2019	9596577	1-1-1712289532	3G	CEILING	PLASTER PEELING	BATHROOM
04/24/2019	9596577	1-1-1712289532	3G	CEILING	PLASTER PEELING	KITCHEN
04/17/2019	9589852	1-1-1708928392	2I	APARTMENTONLY	NO HEAT	ENTIRE APT
03/30/2019	9569738	1-1-1701493382	2H	CABINETS	FALLING	BATHROOM
03/30/2019	9569738	1-1-1701493382	2H	MOLD	N/A	BATHROOM
03/30/2019	9569738	1-1-1701493382	2H	SLOWLEAK	AT WALL/CEIL	BATHROOM
03/30/2019	9569738	1-1-1701493382	2H	OUTLET/SWITCH	OUTLET DEFECT	BEDROOM
03/30/2019	9569738	1-1-1701493382	2H	WINDOW PANE	GLASS BRKN/MISS	KITCHEN
03/14/2019	9547435	1-1-1694607142	2C	WALLS	PEELING	BATHROOM
03/14/2019	9547435	1-1-1694607142	2C	BASIN/SINK	LEAKY PIPE	BATHROOM
03/14/2019	9547435	1-1-1694607142	2C	OUTLET/SWITCH	OUTLET DEFECT	BATHROOM
03/14/2019	9547435	1-1-1694607142	2C	WINDOW FRAME	LOCK BRKN/MISS	ENTIRE APT
03/14/2019	9547435	1-1-1694607142	2C	DOOR	BRKN / MISSING	ENTIRE APT
03/14/2019	9547435	1-1-1694607142	2C	WALLS	PAINT DIRTY	LIVING ROOM
03/14/2019	9547435	1-1-1694607142	2C	WALLS	PAINT DIRTY	BEDROOM
03/14/2019	9547435	1-1-1694607142	2C	FLOOR	BRKN/DEFECTIVE	ENTIRE APT
03/14/2019	9547435	1-1-1694607142	2C	BASIN/SINK	LEAKY PIPE	KITCHEN
03/14/2019	9547435	1-1-1694607142	2C	OUTLET/SWITCH	OUTLET DEFECT	OTHER
03/07/2019	9538489	1-1-1691977852	4I	SLOWLEAK	AT WALL/CEIL	BEDROOM
03/07/2019	9538489	1-1-1691977852	4I	FLOOR	FLR COVR DAMAGE	BEDROOM
03/07/2019	9538486	1-1-1691990172	3G	CEILING	PLASTER PEELING	KITCHEN
03/07/2019	9538486	1-1-1691990172	3G	LIGHTING	DIMS	KITCHEN
03/07/2019	9538486	1-1-1691990172	3G	CEILING	PLASTER PEELING	BATHROOM
03/06/2019	9535369	1-1-1691382802	3I	FLOOR	SAGGING/SLOPING	LIVING ROOM
03/06/2019	9535369	1-1-1691382802	3I	TOILET	TANK-CRACKED	BATHROOM
03/06/2019	9535369	1-1-1691382802	3I	RADIATOR	CRACKED/MISSING	LIVING ROOM
03/02/2019	9529544	1-1-1689749352	F	FLOOR	BRKN/DEFECTIVE	OTHER
03/02/2019	9529544	1-1-1689749352	F	WINDOW FRAME	LOOSE/DEFECTIVE	KITCHEN
03/02/2019	9529544	1-1-1689749352	F	CEILING	COLLAPSING	LIVING ROOM
03/02/2019	9529544	1-1-1689749352	F	CEILING	COLLAPSING	BEDROOM
03/02/2019	9529544	1-1-1689749352	F	WINDOW FRAME	LOOSE/DEFECTIVE	BEDROOM
03/02/2019	9529544	1-1-1689749352	F	CEILING	COLLAPSING	OTHER
02/19/2019	9510470	1-1-1685164432	3B	WINDOW FRAME	WINDOW STUCK	BEDROOM

02/19/2019	9510470	1-1-1685164432 3B	CABINETS	DEFECTIVE	KITCHEN
02/19/2019	9510470	1-1-1685164432 3B	PESTS	MICE	ENTIRE APT
02/19/2019	9510470	1-1-1685164432 3B	FLOOR	TILE BRKN/MISS	KITCHEN
02/19/2019	9510470	1-1-1685164432 3B	PESTS	ROACHES	ENTIRE APT
02/19/2019	9510470	1-1-1685164432 3B	CEILING	CRACKED	BEDROOM
02/19/2019	9510470	1-1-1685164432 3B	WINDOW FRAME	WINDOW STUCK	BATHROOM
02/19/2019	9510470	1-1-1685164432 3B	WALLS	BULGING	BEDROOM
02/11/2019	9498696	1-1-1682111322 2B	MOLD	N/A	BATHROOM
02/11/2019	9498696	1-1-1682111322 2B	WALLS	BULGING	BATHROOM
02/11/2019	9498696	1-1-1682111322 2B	APARTMENTONLY	NO HEAT	ENTIRE APT
02/11/2019	9498696	1-1-1682111322 2B	FLOOR	FLR COVR DAMAGE	BEDROOM
02/11/2019	9498696	1-1-1682111322 2B	CEILING	CRACKED	BEDROOM
02/03/2019	9485729	1-1-1678748362 4G	PESTS	BED BUGS	ENTIRE APT
01/30/2019	9472295	1-1-1677098252 1F	OUTLET/SWITCH	OUTLET DEFECT	KITCHEN
01/30/2019	9472295	1-1-1677098252 1F	CABINETS	DEFECTIVE	KITCHEN
01/30/2019	9472295	1-1-1677098252 1F	PESTS	MICE	ENTIRE APT
01/30/2019	9472295	1-1-1677098252 1F	FLOOR	SAGGING/SLOPING	ENTIRE APT
01/30/2019	9472295	1-1-1677098252 1F	HEAVYFLOW	AT WALL/CEIL	KITCHEN
01/30/2019	9472295	1-1-1677098252 1F	HEAVYFLOW	AT WALL/CEIL	BEDROOM
01/30/2019	9472295	1-1-1677098252 1F	MOLD	N/A	ENTIRE APT
01/01/2019	9408103	1-1-1664626922 F	HEAVYFLOW	AT WALL/CEIL	OTHER
01/01/2019	9408103	1-1-1664626922 F	HEAVYFLOW	AT WALL/CEIL	LIVING ROOM
12/24/2018	9398544	1-1-1661624282 3I	TOILET	BOWL-LEAKING	BATHROOM
12/24/2018	9398544	1-1-1661624282 3I	FLOOR	BRKN/DEFECTIVE	BATHROOM
12/17/2018	9388015	1-1-1659074562 F	FLOOR	HOLE NOWLK AREA	BEDROOM
12/17/2018	9388015	1-1-1659074562 F	FLOOR	SAGGING/SLOPING	BEDROOM
12/17/2018	9388015	1-1-1659074562 F	BATHTUB	CHIPPING/ERODE	BATHROOM
12/17/2018	9388015	1-1-1659074562 F	WINDOW FRAME	LOOSE/DEFECTIVE	ENTIRE APT
12/17/2018	9388015	1-1-1659074562 F	FLOOR	BRKN/DEFECTIVE	OTHER
12/05/2018	9364168	1-1-1654053912 4C	WNGRDBRKN/MSNG	NO CHILD < 11	BEDROOM
12/05/2018	9364168	1-1-1654053912 4C	WINDOW FRAME	WINDOW STUCK	BEDROOM
12/04/2018	9361183	1-1-1653415782 M	CEILING	CRACKED	BATHROOM
12/04/2018	9361183	1-1-1653415782 M	FLOOR	TILE BRKN/MISS	OTHER
12/04/2018	9361183	1-1-1653415782 M	REFRIGERATOR	BROKE DOOR SEAL	KITCHEN
12/04/2018	9361183	1-1-1653415782 M	MOLD	N/A	BATHROOM
12/04/2018	9361183	1-1-1653415782 M	FLOOR	SAGGING/SLOPING	BEDROOM
12/04/2018	9361183	1-1-1653415782 M	WINDOW FRAME	LOOSE/DEFECTIVE	LIVING ROOM
11/27/2018	9349306	1-1-1650555162 3H	MOLD	N/A	KITCHEN
11/27/2018	9349306	1-1-1650555162 3H	CEILING	CRACKED	KITCHEN
11/27/2018	9349306	1-1-1650555162 3H	WINDOW FRAME	WINDOW STUCK	LIVING ROOM
11/27/2018	9349306	1-1-1650555162 3H	LIGHTING	FIXTURE-SPARK	BATHROOM
11/27/2018	9349306	1-1-1650555162 3H	HEAVYFLOW	AT WALL/CEIL	KITCHEN
11/27/2018	9349306	1-1-1650555162 3H	LIGHTING	WATER-PRESENT	LIVING ROOM



[Services](#) |
 [News & Features](#) |
 [City Life](#) |
 [City Agencies](#) |
 [Office of the Mayor](#) |
 [Contact Us](#) |
 [Search](#)

NYC.gov - NEW YORK CITY'S OFFICIAL WEB SITE